

OUT 17216

TOP SECRET

Boch

25X1

T O P S E C R E T

1184

25X1

PASS TO PIC

REF PAGES 40, 41, 42, 43 OF PROJECT HEADQUARTERS DIRECTIVE
50-2055-2, REPORTS CONTROL MANUAL 1 MAY 62.

1. THE FOLWG CHANGE IS EFFECTIVE UPON RECEIPT AND WILL BE
FOLLOWED BY A FORMAL AMENDMENT IN THE NEAR FUTURE.

2. BEGINNING WITH PARA 9. THE CHANGE IS:

A. MSN NUMBER

B. VEHICLE ATTITUDE (ROUGH ORDER OF MAGNITUDE - NO HORIZON

CAMERA)

C. STELLAR CAMERA OPN.

D. TERRAIN CAMERA OPN.

E. CLOCK OPN.

F. FILM TRACKING

G. FIDUCIAL RECORDING

H. FILM SLIPPAGE

I. PRESSURE MARKS ON FILM

J. LIGHT LEAKS ON FILM

TOP SECRET

25X1

-2-

- K. OVERLAP OF TERRAIN FRAMES
- L. TEARING OF FILM
- M. STATIC ELECTRICITY ON FILM
- N. DENSITY OF FILM
- O. CONTRAST OF TERRAIN PHOTOS
- P. GENERAL OR COMPARATIVE RESOLUTION
- Q. GENERAL OR COMPARATIVE GRANULARITY
- R. GENERAL OR COMPARATIVE QUALITY
- S. CLOUD COVER
- T. DATE AND TIME OF EVALUATION.
- U. REMARKS

10. SAMPLE CABLE:

TO: PRITY INFO:

PASS TO PIC

A. 9033A

B. APPEARED NOMINAL EXCEPT FOR TWO FRAMES AT BEGINNING
OF PASS 9 WHICH APPEARED SLIGHTLY LEFT OBLIQUE (ABOUT 5 DEGREES).

C. NORMAL. ACCEPTABLE IDENTIFICATION OF STAR FIELD

D. NORMAL

25X1
25X1
25X1

- E. NORMAL
- F. NORMAL
- G. GOOD. SLIGHT EMULSION BUILD UP ON TERRAIN FIDUCIALS.
- H. NONE
- I. FEA ON LAST PASS.
- J. NONE
- K. ABOUT 10 PERCENT AT BEGINNING OF PASSES AND SIVE
PERCENT AT END OF PASSES.
- L. LAST FRAME ONLY.
- M. VERY LITTLE
- N. MEDIUM
- O. MEDIUM TO LOW
- P. LAND-WATER BOUNDARIES GOOD, CAN DETECT OCCASIONAL
BRIDGE.
- Q. MEDIUM TO FINE
- R. GOOD (OR SLIGHTLY BETTER THAN 9004A)
- S. 45 PERCENT CAT III OR BETTER
- T. 0930 EST - 23 MAY 1961
- U. STAR FIELD RETAINED WITH LITTLE EFFECT ON TERRAIN
QUALITY.

T O P S E C R E T

CFN 1184 -42 40 41 42 43 50-2055-2 1 62 FOLWG A 9 MSN NO

HORIZON OPN OPN OPN FIDUCIAL -42 9033A 9 5 NONE NONE 10

LAND-WATER BRIDGE 9004A 45 CAT III 0930 EST - 23 1961

BT

434. To R: 21/20002